13th final bill

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

225637

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions			Contents	Reference to last Measurement
			Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Name of work:- Desilting of drains & removal of debris & providing Covering Slab for dasarahalli ward No-15.						
	Estimate Cost:- RS 20.00 lakhs.						
	Job Code:- 015-20-000115, P-Code:- 1771						
	W.O No:- EE|DD|W.O|123|2020-21, Dt:05-11-2020.						
	AA No:- EE|DD|AS|87|2020-21, Dt: 09-07-2020						
	TS No:- EE|DD|TS|19|2020-21, Dt: 02-07-2020.						
	Tender Notification No:- BBMP|EE|DD|Ten|12|2020-21, Dt: 28-07-2020						
	Agency:- Sri Muniraj Naik						

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್
ಶ್ರೀ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಪಾ.ಪಾ.ಎಂ.ಪಿ.

Abstract

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
Sl No	Description of work.	unit	Qty		Rate		Amount
2.	Removing & Refixing Stone Slabs.	Sqm	3598.00		97.00		349025.00/-
1.	Earthwork excavation by manual in Ordinary Soil	Cum	1439.01		182.00		261900.00/-
3.	Providing & fixing Precast RCC Slab 100 mm thick	Sqm	622.50		1421.00		884573.00/-
					Sub total	=	1495498.00/-
					GST 12%	=	179460.00/-
					Grand total	=	1674958.00/-
	(Sixteen lakhs Seventy four thousand Nine hundred & fifty eight Rupees)						

[illegible]
30/12/20
[illegible]
560073

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

225638

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Certificate:-						
	1. The work spot has been inspected & the work is found to be necessary.						
	2. The Contractor has done work satisfactorily.						
	3. The Contractor cleared all debris from the work spot.						

30/12/20.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು

ಆರ್. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ

ಬಿಬಿಎಂಪಿ

ಬೆಂಗಳೂರು 560073

Received

AR

30/12/20